
## DIGIRAY



1



2

#### > <u>Different cassette housing</u>

If cassette recognition is an issue with single cassette, the cassette housing need to be replaced.

There exists a RFID tag in the reverse side of cassette housing. Cassette RFID tag contain RFID information such as cassette identification and

size. If Cassette RFID tag is damaged, RFID reader cannot recognize the cassette.



#### RFID board

Page 2 / 3

### **Cassette Recognition Trouble Shooting Guide**

# DIGIRAY

3

If scanner cannot recognize multi cassettes, a RFID board need to be replaced Please refer to the FireCR Flash Service manual for RFID board replacement.

